

**Snohomish County  
CY 2019 Annual Report  
Attachment for Question 84a  
Description of TMDL conditions not complied with**

The County met all TMDL-specific requirements identified in Appendix 2, except the water sample collection aspect of the Swamp Creek surface water monitoring requirement. Due to low flow at the Swamp Creek monitoring location, water samples could not be collected in August or September 2019, resulting in the collection of only 10 of the required 12 samples for 2019.